



Project Penggantian Gland Cable dan Perapihan Cable

Area RTO

No.	Name	Description	Gambar
1	No.1 Air Knife Blower	Konektor Flexible Conduit to box 3/4 inch For Incoming power motor	
2	No.2 Air Knife Blower	Konektor Flexible Conduit to box 3/4 inch For Incoming power motor	

3	Chemical Exhaust Blower	Konektor Flexible Conduit to box 1 1/2 inch For Incoming power motor	
4	RTO Combustion Blower	Konektor Flexible Conduit to box 3/4 inch For Incoming power motor	

5	RTO Purging Fan	Konektor Flexible Conduit to box 1/2 inch For Incoming power motor	
6	No.1 Hot Water Pump	Konektor Flexible Conduit to box 3/4 inch For Incoming power motor	

7	No.2 Hot Water Pump	Konektor Flexible Conduit to box 3/4 inch For Incoming power motor	
8	Coater Room Exhaust Fan	Konektor Flexible Conduit to box 3/4 inch For Incoming power motor	

9	Coater Room Air Supply	Konektor Flexible Conduit to box 1 1/2 inch For Incoming power motor	
10	Fresh Air Suplly	Konektor Flexible Conduit to box 3/4 inch For Incoming power motor & Konektor Flexible Conduit to box 1/2 inch For Incoming power Fan	

11	ID Fan	Konektor Flexible Conduit to box 2 1/2 inch For Incoming power motor & Konektor Flexible Conduit to box 1/2 inch For Incoming power fan	
----	--------	--	---

Note :

- 1 Konektor gland cable yang terpasang diganti dengan standart mengikuti ukuran kabel dan flexible conduit
- 2 Box Motor dimodifikasi disesuaikan dengan kebutuhan spare part
- 3 Penambahan pemasangan Cable Gland Shroud Kondom Merk CMP exproof M63 untuk mencegah masuk air ke box
- 4 Estimasi pengerjaan menyesuaikan dengan kondisi line
- 5 Butuh suport tim project untuk modifikasi