

**Preventive Connection, Cleaning, Tightening Motor dan Fan Hot Water No 2 Wringer Roll Check,
Verifikasi, dan Cleaning Position sensor wringer roll hot water rinse, Check dan Verifikasi
Pneumatic Solenoid Valve Wringer roll Hot water rinse**

Pada tanggal 11/09/2024 Hilmy, Wawan dan Amay mengerjakan Preventif motor dan Fan, Lalu Check dan Verifikasi Pneumatic Solenoid Valve Wringer roll Hot water rinse berikut kegiatan dibawah ini:

